



Wiring Diagrams for 2-Wire Miniature Head Temperature/Process Transmitters


ETM1 Non-Isolated




ETM2 Isolated




Input Connections for ETM1 and ETM2



Thermocouple




RTD- PT100, PT1000
3-wire




RTD- PT100, PT1000
4-wire


Additional Input Connections for Isolated ETM2



mV




Potentiometer 3-wire




Potentiometer 4-wire

Output Connections for ETM1 and ETM2



ETM1



ETM2